PICOOC®

PICOOC Smart Scale

User Manual

Please read this User Manual carefully, before using the device.





English

Maintenance

- Do not use such as hot water or corrosive cleaning agents to scrub the product. When it becomes dirty, please clean it with a soft cloth dampened with water, then wipe it with a dry cloth.
- Do not disassemble or clean with water.
- Do not keep this product in a humid place, such as bathroom or restroom.
- Do not leave the batteries in for an extended period of time without using the product. Store the product properly.
- Please use it on a hard and flat surface. Do not put other items at the bottom of the scale.
- During use, do not scratch the scale surface with any hard object, to avoid affecting the measurement accuracy.

* Please keep this instruction manual properly. Anyone using this product should read through this manual beforehand. This product should be accompanied by a copy of this instruction manual when it is sold

Weighing Small Objects

① **Place the product on a hard and flat platform. Press the scale surface and wait for the surface to display 0.00**

② **Place a small object to be weighed in the center of the scale surface. The display panel will show the weight of the object in real time**

- Small Object Weighing Range: 500g-10kg
- Small Object Weighing Division Value: 10g

* If reinstalling the batteries or switching the power on when the product is in use, please measure your body weight first, followed by weighing the small object

Warranty and Support

You may consult your dealer for warranty and service support policies of the device
You may check the dealer information on supporting websites and learn about more information of the device.(http://www.picooc.com)

Русский

Уход за устройством

- Не используйте горячую воду или агрессивные чистящие средства для чистки весов. При загрязнении, протрите весы мягкой тканью, смоченной водой, а затем сухой тканью.
- Не разбирайте весы и не мойте их в воде.
- Не храните весы во влажном месте, например, в ванной или туалете.
- Не оставляйте батарейки в весах, когда они не используются длительное время.
- Всегда выполняйте взвешивание на твердой, ровной и плоской поверхности.
  Не подкладывайте предметы под весы.
- Не допускайте появления царапин на поверхности весов — это может повлиять на точность измерений.

* Данная инструкция должна входить в комплектацию каждого экземпляра весов. Каждому пользователю рекомендуется заранее прочитать инструкцию.

Взвешивание мелких предметов

① **Установите весы на твердую, ровную и плоскую поверхность. Нажмите на платформу весов и дождитесь, пока на весах отобразится 0,00.**

② **Поместите небольшой предмет для взвешивания в центр платформы. На дисплее отобразится вес объекта.**

- Диапазон взвешивания мелких предметов: 0,5–10 кг.
- Шаг измерения при взвешивании мелких предметов: 10 г.

* После замены батареек или включения питания во время первого использования сначала измерьте вес своего тела, а затем взвесьте небольшой предмет.

Гарантии и техническая поддержка

Для знакомства с гарантийными условиями и условиями технического обслуживания вы можете проконсультироваться со своим дилером.
Вы можете ознакомиться с информацией о дилерах, а также узнать больше об устройстве на соответствующем веб-сайте: picooc.ru.

PICOOC®

PICOOC Technology Co., Ltd.

PICOOC is a trademark of PICOOC Technology Co., Ltd.

Room 405, A Building, No.28, Xinjiekou Outer Street, Xicheng District, Beijing, China

Made in China.

V 202201V1

EAC CE RoHS