



BTW 6.2.1.0900

Release Notes

October 22, 2009

Confidential and Proprietary Information

© Broadcom Corp., 2008, All rights reserved.
Printed in United States of America.
16340 West Bernardo Drive
San Diego, CA 92127
Phone: (858) 385-8800
Fax: (858) 385-8810

LICENSED SOFTWARE

©200x Broadcom Corporation

This program is the proprietary software of Broadcom Corporation and/or its licensors, and may only be used, duplicated, modified or distributed pursuant to the terms and conditions of a separate, written license agreement executed between you and Broadcom (an "Authorized License"). Except as set forth in an Authorized License, Broadcom grants no license (express or implied), right to use, or waiver of any kind with respect to the Software, and Broadcom expressly reserves all rights in and to the Software and all intellectual property rights therein. IF YOU HAVE NO AUTHORIZED LICENSE, THEN YOU HAVE NO RIGHT TO USE THIS SOFTWARE IN ANY WAY, AND SHOULD IMMEDIATELY NOTIFY BROADCOM AND DISCONTINUE ALL USE OF THE SOFTWARE.

Except as expressly set forth in the Authorized License,

1. This program, including its structure, sequence and organization, constitutes the valuable trade secrets of Broadcom, and you shall use all reasonable efforts to protect the confidentiality thereof, and to use this information only in connection with your use of Broadcom integrated circuit products.
2. TO THE MAXIMUM EXTENT PERMITTED BY LAW, THE SOFTWARE IS PROVIDED "AS IS" AND WITH ALL FAULTS AND BROADCOM MAKES NO PROMISES, REPRESENTATIONS OR WARRANTIES, EITHER EXPRESS, IMPLIED, STATUTORY, OR OTHERWISE, WITH RESPECT TO THE SOFTWARE. BROADCOM SPECIFICALLY DISCLAIMS ANY AND ALL IMPLIED WARRANTIES OF TITLE, MERCHANTABILITY, NONINFRINGEMENT, FITNESS FOR A PARTICULAR PURPOSE, LACK OF VIRUSES, ACCURACY OR COMPLETENESS, QUIET ENJOYMENT, QUIET POSSESSION OR CORRESPONDENCE TO DESCRIPTION. YOU ASSUME THE ENTIRE RISK ARISING OUT OF USE OR PERFORMANCE OF THE SOFTWARE.
3. TO THE MAXIMUM EXTENT PERMITTED BY LAW, IN NO EVENT SHALL BROADCOM OR ITS LICENSORS BE LIABLE FOR (i) CONSEQUENTIAL, INCIDENTAL, SPECIAL, INDIRECT, OR EXEMPLARY DAMAGES WHATSOEVER ARISING OUT OF OR IN ANY WAY RELATING TO YOUR USE OF OR INABILITY TO USE THE SOFTWARE EVEN IF BROADCOM HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES; OR (ii) ANY AMOUNT IN EXCESS OF THE AMOUNT ACTUALLY PAID FOR THE SOFTWARE ITSELF OR U.S. \$1, WHICHEVER IS GREATER. THESE LIMITATIONS SHALL APPLY NOTWITHSTANDING ANY FAILURE OF ESSENTIAL PURPOSE OF ANY LIMITED REMEDY.

INTRODUCTION

CUSTOMER SUPPORT PORTAL (CSP)

Customers can submit enhancements, changes and/or defects against releases of software or firmware via the Broadcom Customer Support Portal (CSP). CSP cases are replicated into the Broadcom Bluetooth engineering change management database for review by the engineering community and change control boards.

If your project or program is not listed inside the CSP please contact your Broadcom representative whom can configure the CSP system for use with your unique needs.

To start using the CSP please visit <http://support.broadcom.com>.

Installation Command Line Options

To install BTW from command line prompt or from a batch file, use the following command line options:

Setup.exe [/qn | /qb | /qr] [/nw] [/nodfu] [/L<LangId>] [/ru] [/ri]

/qn - Silent install without any UI and user interaction

/qb - Silent install with basic UI with progress dialog without any user interaction

/qr - Silent install with full UI without any user interaction

/nw- Setup.exe does not wait for BTW install to complete, exits after invoking MSI install.

/nodfu- Do not execute DFU during BTW install (even if configured for DFU in SvcPack.ini file)

/noinf - Do not install USB inf file, bcbtums*.inf for Vista and btwusb.inf for XP. (Newly added since 5.5.0.900 and 6.1.0.2800)

/L -Installation language

<LangId> can be one of the following

1033: English

1046: Portuguese (Brazilian)

1028: Chinese Tradition

2052: Chinese Simplified

1030: Danish

1043: Dutch

1035: Finnish

1036: French

1031: German

1040: Italian

1041: Japanese

1042: Korean

1044: Norwegian

1034: Spanish

1053: Swedish

1049: Russian

1045: Polish

14337: Arabic

1029: Czech

1032: Greek

1037: Hebrew

1050: Croatian

1038: Hungarian

2070: Portuguese (European)

1048: Romanian

1055: Turkish

/ru - Suppress reboot at the end of uninstall. (Relevant for Windows 98 and ME during upgrade)

/ri - Suppress reboot at the end of install (Relevant for Windows 98 and ME and if reboot is required on Windows 2000).

For example, to install silently without any UI in German language, use the following command line

setup.exe /qn /L1031

Signed Driver Report

Folder: v:\BTW\btw1.2\bin\drivers

Driver: Signed? Signature: Valid? SubmissionID: Version:

Driver:	Signed?	Signature:	Valid?	SubmissionID:	Version:
btusbflt.cat	Yes	WHQL	Yes	1332974	6.3.0.300
btwaudio.cat	Yes	WHQL	Yes	1358570	6.2.1.800
btwavdt.cat	Yes	WHQL	Yes	1347316	6.2.1.200
btwrchid.cat	Yes	WHQL	Yes	1347320	6.2.1.200
frmupgr.cat	Yes	WHQL	Yes	1334946	6.2.0.9500
btwl2cap.cat	Yes	WHQL	Yes	1334971	6.2.0.9500
btwsecfl.cat	Yes	WHQL	Yes	1335503	6.2.0.9451
bcbthid32.cat	Yes	WHQL	Yes	1340928	6.2.0.9800
bcbtums-Vistax86-brcm.cat	Yes	WHQL	Yes	1353786	6.2.0.9407
bcbtums-win7x86-brcm.cat	Yes	WHQL	Yes	1353786	6.2.0.9407

Folder: v:\BTW\btw1.2\bin\amd64\drivers

Driver: Signed? Signature: Valid? SubmissionID: Version:

Driver:	Signed?	Signature:	Valid?	SubmissionID:	Version:
btusbflt64.cat	Yes	WHQL	Yes	1332974	6.3.0.300
btwaudio64.cat	Yes	WHQL	Yes	1358570	6.2.1.800
btwavdt64.cat	Yes	WHQL	Yes	1347316	6.2.1.200
btwrchid64.cat	Yes	WHQL	Yes	1347320	6.2.1.200
frmupgr64.cat	Yes	WHQL	Yes	1334946	6.2.0.9500
btwl2cap64.cat	Yes	WHQL	Yes	1334971	6.2.0.9500
btwsecfl64.cat	Yes	WHQL	Yes	1335503	6.2.0.9451
bcbthid64.cat	Yes	WHQL	Yes	1340928	6.2.0.9800
Bcbtums-Vistax64-brcm.cat	Yes	WHQL	Yes	1353786	6.2.0.9407
bcbtums-win7x64-brcm.cat	Yes	WHQL	Yes	1353786	6.2.0.9407

BTW 6.2.1.0900

Resolved Defects

Major

BLTH00211205

Subsystem: Other

Headline:

BTW recovery button wizard re-starts after pairing

Release Note:

Fixed bug on final wizard page to check for whether or not mouse was paired and connected.

Resolved Defects

Minor

BLTH00210345

CSP-261943

Subsystem: Other

Headline:

The device name of DBCS is garbled.

Release Note:

fixed using utf8 for device name encoding

CSP URL:

<https://support.broadcom.com/IMS/Main.aspx?Page=MyCasesDisplay&IssueID=261943>
